



Graphite Quick Reference Card

Easy tear-out Graphite Quick Reference Card

The screenshot shows the Graphite v8 software interface with the following components labeled:

- Selection Tools:** Includes Triad, Line Tools, Arc Tools, Circle Tools, Ellipse Tools, Poligone Tools, Spline Tools, Text Tools, Dimension Tools, Fillet and Chamfer Tools, Trim Tools, Transform and Duplicate Tools, View Tools, and Miscellaneous Tools.
- Bill of Materials:** A vertical toolbar containing various material and object management icons.
- Navigator Palette:** A window showing a top-down view of the current object.
- Edit Object Window:** A panel for editing the properties of a selected object (1 line). Properties include: Locked (unlocked), Layer (Layer1), Color (Black), Pattern (Solid), Weight (.002"), Control Pts (hidden), Point 1.x (-2,555), Point 1.y (3,409), Point 1.z (0), Point 2.x (-1,945), Point 2.y (2,799), Point 2.z (0), Length (.862), length/2 (.431), and Angle (-45°).
- Layers Window:** A panel for managing layers. It lists Constraints, Construction, Dimension, and Layer1 (selected). Buttons include New, Delete, Hide, Set Layer, and Rename.
- Layer Groups Window:** A panel for managing layer groups. It shows a list of groups: Constraints, Construction, Dimension, and Layer1 (selected). Buttons include New, Delete, Set Group, and Rename.
- Pen Style Palette:** A toolbar for selecting different pen styles.
- Dimensions Palette:** A toolbar for selecting different dimension styles.
- Status Line:** Displays coordinates and dimensions. X: -2,555, Y: 3,409, Z: 0, dx: .609, dy: -.609, dz: 0, Length: .862, Angle: -45°.



Graphite Quick Reference Card

Special Characters

Special drafting symbols and characters are accessed from the keyboard. For a complete list of these characters see Appendix B in the User Guide.

Windows

Hold down the ALT key and type the desired numeric code:

Mark	Key Combination
°	ALT 0176
∅	ALT 0216
±	ALT 0177

Macintosh

Hold down the Option key and type the desired numeric code:

Mark	Key Combination
é	OPTION+e then letter to be accented
è	OPTION+` then letter to be accented
ñ	OPTION+n then letter to be accented
ü	OPTION+u then letter to be accented

The following list includes common symbols which are available in all fonts.

Mark	Key Combination
°	OPTION+ SHIFT 8
∅	OPTION+ O (letter or number)
±	OPTION+SHIFT =

